

| | |
|--------------|--------------|
| Bulletin No. | R_08_2020 |
| Date | October 2020 |

Motor Kit F80s Compact / Plus

Dear customer,



we inform you that the products
Motor Kit F80s Compact / Plus:

**Item No. 07929-01-
Item No. 07929-01T
Item No. 07929-01H
Item No. 07929-02-
Item No. 07929-02T
Item No. 07929-02H**

**marked with S/N < 020-293-256
and yellow label on the box packaging
with nr. 56191020**

Could create a slight defect in the closing
of the awning, not guaranteeing the correct
contact of the microswitch.

If the above mentioned problem occurs,
Fiamma invites you to communicate to the
assistance department the S/N and the no. of
the yellow label on the packaging, in order to
proceed with the replacement of the end cap,
part of the above mentioned Kit.



S/N < 020-293-256

variable digits